

## Workplace Health and Safety Violations Categories

Hazards in workplaces occur when the working environment and unsafe practices of individuals lead to property damage, injuries or accidents. Identifying and eliminating these unsafe practices is a major component of maintaining a safe workplace. The below violations/unsafe practices list is based on the risk level as the following:

LOW RISK						
Fine amount from 500 AED						
1.	Materials stacking that blocks the passageway and surrounding service lift.	<ol> <li>Not wearing task-specific PPE (Personal Protective Equipment: safety helmet, safety vest, protective glasses etc.).</li> </ol>				
3.	Smoking in non-specified area.	4. Un authorized access to restricted area.				
5.	Failure to label or put up warning sign for hazardous material.	6. Using of fire exit for the common access.				
7.	Housekeeping of working area is not maintained.	<ol> <li>Working without inspection of equipment's</li> </ol>				
9.	Unauthorized use of washrooms and other facilities.	10. Failure to attend tool box talks prior to commencing work.				
11.	. Violation of waste disposal, air pollution, water pollution, or noise control.	12. Failure to comply with floor loadings in the venue.				
13	. No corrections made after several verbal warnings.	14. Failure to report an accident and provide written documentation to the property manager.				
15	. Failure to dispose the waste material debris to assigned locations.	16. Unsafe acts (others).				



## **MEDIUM RISK**

Г

FINE AMOUNT IS <b>750 AED</b>					
17. Consuming products that are against the law that cause harm to oneself or others while on site.	<ol> <li>First alarm activation due to contractor activity and not requesting to silence the fire alarm.</li> </ol>				
19. Unsafe live edges protection while during construction during buildup and tear down.	20. Unauthorized noisy works during office working hours.				
21. Improper use of ladders.	22. Open trenches cover and pits without warning signages.				
23. Improper connection to the electricity, water, and gas without proper approval.	24. Unable to get work permit for all kinds of operations.				
25. Unsafe dismantling during tear down.	26. No supervision of work force on site.				
27. Violation of waste disposal in the designated areas. Violation of air pollution, water pollution, or noise control.	28. Unsafe driving, speeding, carrying unsecure load, dangerous load of equipment or machines (boom lift, scissor lift, crane).				
29. No licenses to operate plant and specialist equipment.	30. Unsafe acts at heights.				
<ul> <li>31. Failure to follow the additional safety precautions outlined by the Venue Health &amp; Safety Inspector after the second warning has been issued.</li> </ul>	32. Used of unrated lifting eyebolts for all hanging points				
33. Unsafe acts (others)					

HIGH RISK					
Fine amount 1000 AED					
34. Failure to secure items while working at	35. Causing a fire accident on site.				
heights.	55. Causing a fire accident of site.				
36. Failure to provide adequate protection of					
flow ducts and other electrical equipment	37. Exposed live electrical cables.				
while installing a water feature/ display.					
38. Use of damaged and un-rated wire rope	39. Stand collapse.				
or slings during construction.					



		DUBAIW	
40. Improper storage of high-pressured 41. Unsafe Electrical direct connectio			
	cylinders.	socket.	
	42. Improper storage of flammable materials.	43. Illegal burning of material.	
	44. Use of damaged or unsafe wiring	45. Failure to obtain safety permits (Hot work	
	including wire size and proper	permits, confined space permit, roof	
termination of connections.		permit).	
46. Failure to provide ventilation in confined		47. Failure of the structure due to a lack of	
	spaces	temporary supports	
	48. Unsafe acts (others).		

## Health and Safety Violations Risk Matrix

		How Likely?		
		Very Likely	Somewhat Likely	Not likely
5	Death or permanent disability	High	High	Medium
What Harm?	Temporary disability or illness	High	Medium	Low
	Minor injury/damage	Medium	Low	Low